



In order to send AUTOCAD drawings to W.A. Wilson for cut glass, the following rules must be followed.

- Drawing must be done in inches
- Only one (1) pattern per file
- Use simple entities, like LINE and ARC
- Make sure the shape is closed (no gap between last end point and next start point for each entities)
- If you use POLYLINE as a block, you need EXPLODE it to individuals
- File type must be DXF
- Call W.A.Wilson to find out which CSR you will be e-mailing your file. If you send the e-mail without calling first, you are running the risk that that CSR maybe out of the office and your order will not be entered.